

PHOTO DOCUMENTATION



PHOTO 1: Residence located on northeast portion of the subject property looking east from driveway.



PHOTO 2: Above-ground heating oil tank located on the southeast corner of the residence.



PHOTO 3: Abandoned vehicle located on the west side of the driveway and one of the concrete pads observed on site (looking west).



PHOTO 4: Mowed area located to the southwest of the residence, looking south.



PHOTO 5: Wooded area near the mowed/cleared area looking generally southeast.



PHOTO 6: View of Fairview Creek located to the east of the residence along the east property boundary.



PHOTO 7: Weir on Fairview Creek near NE Halsey Street on northeast corner of subject property.



PHOTO 8: Trailer park located on the east side of the creek.



PHOTO 9: North boundary of subject property on NE Halsey Street looking west.



PHOTO 10: Stored vehicles and boats along center property boundary looking west from driveway of the residence to the west.



PHOTO 11: Residence located near the center of the subject property (*not* a part of the subject property) looking north toward NE Halsey Street.



PHOTO 12: Portion of the boulder retaining wall on west side of subject property.



PHOTO 13: Pile of boulders near southeast corner of subject property near the apartments on the south side, looking north.



PHOTO 14: south side of subject property near southwest corner of site, looking north.